

Work Order ID 80259-2

February-15-12 3:34:19 PM

80259

Page 1

Item ID: D3560-041
Revision ID:
Item Name: Arm Weldment

Accept

N900040100

Setup Start *NS1*
Stop *NS2*

Start Date: 15/02/2012 Start Qty: 10.00
Required Date: 29/02/2012 Req'd Qty: 10.00

10 9 4
10 9 4

Cust Item ID:
Customer:

Reference:

Approvals: Process Plan: *M.L.J.*
QC:

Date: 12/02/16 Tooling:
Date: SPC (Y/N):

Date:
Date:

Run Start *NR1*
Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D3560	Rev D								

100

100

Bandsaw

Jeaspa Bandsaw

BAND SAW

Memo

Cut blanks 16.750" long

0.00

0.00

12/03/09

10 10

110

110

HAAS I

HAAS CNC vertical machine #1

HAAS CNC VERTICAL MACHINING #1

Memo

1- Mill as per Folio FA693 Rev: *AK* & Dwg D3560 Rev: *D*
2-C'sink 0.196" hole on manual mill as per dwg D3560
3-Deburr per dwg D3560

0.00

0.00

12-3 12 10

12-03-15

120

120

QC

Quality Control

QC2- Inspect parts off machine FAI/FAIB

Memo

0.00

0.00

12-3 12 10

Work Order ID 80259

80259

Page 2

February-15-12 3:34:19 PM

Item ID: D3560-041

Accept

N900040100

Setup Start *NS1*

Revision ID:

Stop *NS2*

Item Name: Arm Weldment

Start Date: 15/02/2012 Start Qty: 10.00

10

Cust Item ID:

Required Date: 29/02/2012 Req'd Qty: 10.00

10

Customer:

Reference:

Run Start *NR1*

Approvals: Process Plan:

Date:

Tooling:

Date:

Stop *NR2*

QC:

Date:

SPC (Y/N):

Date:

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

130

QC8- Inspect parts - second check

0.00

Da 12/03/12

10

0

130

QC

Memo

0.00

Quality Control

140

Large Fab

0.00

5

0

12-08-01

140

Large Fab

Memo

0.00

Large Fab

1-Weld assembly as per dwg D3560

STEP:

1- clean material (buff bracket and bottom of arm with blue pad)

2- set up bracket and arm on jig

3- preheat bracket and arm with torch

4- clean before welding with brush

5- set up machine to 135 amps

6- weld across bottom and top ends

7- reheat with torch (65 deg C)

8- on one side weld from bottom to top half way

9- same for other side (half way)

10- from half way point weld the rest of the first side (ease off pedal near end)

11- same for remaining side (ease off pedal near end)

Allen-Rod # 122/30



Work Order ID 80259

80259

Page 3

February-15-12 3:34:19 PM

Item ID: D3560-041

Accept

N900040100

Setup Start *NS1*

Revision ID:

Stop *NS2*

Item Name: Arm Weldment

Start Date: 15/02/2012 Start Qty: 10.00

10

Cust Item ID:

Required Date: 29/02/2012 Req'd Qty: 10.00

10

Customer:

Reference:

Run Start *NR1*

Approvals: Process Plan:

Date:

Tooling:

Date:

Stop *NR2*

QC:

Date:

SPC (Y/N):

Date:

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

150

QC5- Inspect part completeness to step on W/O

0.00

150

QC

Memo

0.00

Quality Control

5 12.8.1 DAS 24 8-8

160

QC9- Inspect visual per QSI004- Fusion Welds

0.00

160

QC

Memo

0.00

Quality Control

5 0 12/08/01 DAS 13 8-8

170

Chemical Conversion Coat per QSI005 4.1

0.00

170

HandFinish

Memo

0.00

Hand Finishing

5 0 12.08-01

Work Order ID 80259

February-15-12 3:34:19 PM

80259

Page 4

Item ID: D3560-041

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Arm Weldment

Start Date: 15/02/2012 Start Qty: 10.00

10

Cust Item ID:

Required Date: 29/02/2012 Req'd Qty: 10.00

10

Customer:

Reference:

Run Start ***NR1***

Approvals: Process Plan:

Date:

Tooling:

Date:

Stop ***NR2***

QC:

Date:

SPC (Y/N):

Date:

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

180

QC3- Inspect Part Finish

0.00

180

QC

Memo

0.00

Quality Control

5

[Signature]

[Signature]
12.08.01

190

Small Fab

0.00

190

Small Fab

Memo

0.00

Small Fab

1-Press bushing in D3560 arm per dwg D3562

5x

[Signature]
12/08/02

200

QC5- Inspect part completeness to step on W/O

0.00

200

QC

Memo

0.00

Quality Control

Smb
12.8.02

DAS
16
2-03

12/08/02

5

250
(10)

Work Order ID 80259

February-15-12 3:34:19 PM

80259

Page 5

Item ID: D3560-041

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Arm Weldment

Start Date: 15/02/2012 Start Qty: 10.00

10

Cust Item ID:

Required Date: 29/02/2012 Req'd Qty: 10.00

10

Customer:

Reference:

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
---------	--------	-----------	------------	------------	---------------	-------------

210

Identify as per dwg & Stock Location: CJA

0.00

210

Packaging

Memo

0.00

Packaging

*** STOCK IN STEP CELL ***

5 0 Ac
12-08-02

220

QC21- Final Inspection - Work Order Release

0.00

220

QC

Memo

0.00

Quality Control

12/8/3 JD

u12-08-03

Picklist Print

February-15-12 3:34:23 PM

Page 1

Work Order ID: 80259

80259

Parent Item: D3560-041

D3560-041

Parent Item Name: Arm Weldment

Start Date: 15/02/2012

Required Date: 29/02/2012

Start Qty: 10.00

Required Qty: 10.00

Comments: IPP Rev:A New Issue 07.05.24 EC
IPP rev B ECN 987 07.10.09 EC verified by: DD
IPP Rev:C ECN1048 07-12-18 DD verified by: EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D2808

Manufactured

No

100

Each

70.0000

1

10

D2808

Bushing

**

Location

Loc Qty

Loc Code

GA

70

32896

2

76188

3

78950

24

79688

41

M6061T6B0.500X05.00

Purchased

No

140

f

51.2274

1.395

14.68421

M6061T6B0 500X05 000

6061-T6 Bar .500 x 5.00

**

Location

Loc Qty

Loc Code

MAT001

21.834

112154

6.935

117933

2.123

119346

12.776

MAT004

29.3934

120243

24

→ 120421

5.3934

M120866

X12

2.8

OK 12/03/07

Picklist Print

February-15-12 3:34:23 PM

Work Order ID: 80259

Parent Item: D3560-041

Parent Item Name: Arm Weldment

80259

D3560-041

Start Date: 15/02/2012

Required Date: 29/02/2012

Start Qty: 10.00

Required Qty: 10.00

D3592-1

Manufactured No

190

Each

27.0000

1

10

D3592-1

Plate

**

12.08.01

Location

Loc Qty

Loc Code

WA

380319

4

78934

4

WA002

23

47015

2

78934

21

5

DART AEROSPACE LTD		Work Order:	
Description: Arm		Part Number:	D3560-1
Inspection Dwg: D3560 Rev: D		Page 1 of 1	

FIRST ARTICLE INSPECTION CHECKLIST


☒ First Article ☐ Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	.5070	-			
Ø0.196	+0.005/-0.001	.196	-			
Ø1.000	+0.010/-0.001	1.004	✓			
0.500	+/-0.010	.496	-			
0.250	+/-0.010	.249	-			
0.275	+/-0.010	.274	-			
0.188	+/-0.010	.190	-			
2.000	+/-0.010	2.000	-			
1.700	+/-0.010	1.700	-			
Ø0.385 x 100°	+/-0.010 x 0.5°	.385 x 100°	-			
0.250 Deep	+/-0.010	.252	-			


Measured by: <i>[Signature]</i>	Audited by: <i>[Signature]</i>	Prototype Approval:	N/A
Date: 12-3-15	Date: 12/03/16	Date:	N/A

Rev	Date	Change	Revised by	Approved
A	07.01.17	New Issue P/O D3560-041	KJ/JLM	
B	07.06.13	Dimensions updated per Dwg Rev B	KJ/JLM	
C	08.07.24	Dwg Rev updated	KJ/DD <i>[Signature]</i>	<i>[Signature]</i>


RELEASED
07.12.16



D3560-041 ARM WELDMENT



D3560-042 ARM WELDMENT




D3560-043 ARM WELDMENT



D3560-044 ARM WELDMENT

80259 M.C.J
12/02/16



**DETAIL A
SCALE 1 : 2**





PLATE
(REF)



**DETAIL B
SCALE 1 : 2**

PARTS LIST

QTY -041	QTY -042	QTY -043	QTY -044	P/N	DESCRIPTION
X				D3560-041	ARM WELDMENT
	X			D3560-042	ARM WELDMENT
		X		D3560-043	ARM WELDMENT
			X	D3560-044	ARM WELDMENT
1	1	1	1	D2808	SPACER
1				D3560-1	ARM
	1			D3560-2	ARM
		1		D3560-3	ARM
			1	D3560-4	ARM
1	1	1	1	D3592-1	PLATE

- NOTES:**
 1) MATERIAL: N/A
 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 5) BREAK SHARP EDGES: 0.005 TO 0.015 MAX
 6) IDENTIFICATION: N/A
 7) WEIGHT: 1.23 lbs (TYP)
 8) WELDING: PER DART QSI 004


D	ADD D2808 PRESS FIT NOTE: REDRAWN IN SOLIDWORKS	DC	07.11.16
C	REMOVE POWDER COAT	CP	07.06.10
B	REDESIGN AS WELDMENT, ADD POCKETS	CP	07.01.16
A	NEW ISSUE	CP	06.09.25
REV.	DESCRIPTION	BY	DATE
DESIGN			
DRAWN			
CHECKED			
MFG. APPR.			
APPROVED			
DE APPR.			
DATE	07.11.16		

DART AEROSPACE LTD
HAWKESBURY, ONTARIO, CANADA

DRAWING NO. **D3560** REV. D
SHEET 1 OF 5
TITLE **ARM WELDMENT** SCALE 1:4

COPYRIGHT © 2006 BY DART AEROSPACE LTD
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS UNDERSTANDING THAT IT IS NOT TO BE USED FOR ANY PURPOSES OR COPIED OR REPRODUCED IN ANY MANNER WITHOUT THE WRITTEN PERMISSION FROM DART AEROSPACE LTD.

80259



D3560-1 ARM WELDMENT


- NOTES:
- 1) MATERIAL: 6061-T6 (OR 6061-T651/T6510/T6511/T62) BAR, 0.500 THICK
PER AMS-QQ-A-225/8 (OR AMS 4117/4128/4115/4116) OR
PER AMS-QQ-A-200/8 (OR AMS 4160)
(REF. DART SPEC. M6061T6B0.500)
 - 2) FINISH: NONE
 - 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: 0.005 TO 0.015 MAX
 - 6) IDENTIFICATION: N/A
 - 7) WEIGHT: 1.05 lbs

DESIGN	JP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	JC		
CHECKED	JP	DRAWING NO.	REV. D
MFG. APPR.	JP	D3560	SHEET 2 OF 5
APPROVED	JP	TITLE	SCALE
DE APPR.	JP	ARM WELDMENT	1:2
DATE	07.11.16	COPYRIGHT © 2008 BY DART AEROSPACE LTD <small>THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT NOT BE USED FOR ANY PURPOSE FOR COP OR COMMUNICATION TO ANY OTHER PERSON OR ENTITY WITHOUT THE WRITTEN PERMISSION OF DART AEROSPACE LTD.</small>	

RELEASED
07.12.16




80259



PROFILE TO MATCH
D3592-1 PLATE,
MACHINE AT 2.4°,
SEE VIEW D-D


D3560-2 ARM

- NOTES:
- 1) MATERIAL: 6061-T6 (OR 6061-T651/T6510/T6511/T62) BAR, 0.500 THICK
PER AMS-QQ-A-225/8 (OR AMS 4117/4128/4115/4116) OR
PER AMS-QQ-A-200/8 (OR AMS 4160)
(REF. DART SPEC. M6061T6B0 500)
 - 2) FINISH: NONE
 - 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 - 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 - 5) BREAK SHARP EDGES: 0.005 TO 0.015 MAX
 - 6) IDENTIFICATION: N/A
 - 7) WEIGHT: 1.05 lbs




DESIGN	JP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	JC		
CHECKED	JP	DRAWING NO.	REV. D
MFG. APPR.	JP	D3560	SHEET 3 OF 6
APPROVED	AMP	TITLE	SCALE
DE APPR.	JP	ARM WELDMENT	1:2
DATE	07.11.16	COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE REPRODUCED OR FOR ANY PURPOSE OR COMMUNICATED TO ANY OTHER PERSON OR ENTITY WITHOUT PERMISSION FROM DART AEROSPACE LTD.	

80255



80259



D3560-4 ARM

DESIGN		DART AEROSPACE LTD	
DRAWN	PC	HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO. D3560	REV. D
MFG APPR		TITLE ARM WELDMENT	SHEET 5 OF 5
APPROVED		SCALE 1:2	
DE APPR		COPYRIGHT © 2006 BY DART AEROSPACE LTD	
DATE	07.11.16	THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS UNDERSTANDING THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR REPRODUCED IN ANY FORM WITHOUT THE WRITTEN PERMISSION FROM DART AEROSPACE LTD.	